

### For Sales Enquiry

Mr. Mohan Singh

(GM - Sales)

**Ph :** +91 9971980667

[info@bahubalimachines.com](mailto:info@bahubalimachines.com)

Mr. Parag Jain

(M.D)

**Ph :** +91 9810259321

[bahubali@bahubalimachines.com](mailto:bahubali@bahubalimachines.com)

### Address

D-5, Bulandshar Road Ind. Area,

Ghaziabad, UP (India),

**Ph :** +91 120 4376060, +91 120 4377070

[www.bahubalimachines.com](http://www.bahubalimachines.com)

**Gear Cutting Machine**

**Bevel Gear Machine**

| Sr No | Machine Name | Make     | Model        |
|-------|--------------|----------|--------------|
| 1     | 1031         | OERLIKON | SKM1         |
| 2     | 1032         | OERLIKON | SKM1         |
| 3     | 1033         | GLEASON  | 116          |
| 4     | 1034         | GLEASON  | 116          |
| 5     | 1035         | GLEASON  | 16           |
| 6     | 1036         | STANKO   | STANKO160SP  |
| 7     | 1037         | GLEASON  | 726REVACYCLE |
| 8     | 1039         | STANKO   | 320          |
| 9     | B24          | GLEASON  | 12           |
| 10    | B47          | STANKO   | E3C-0642     |

**Centring and Facing machine**

| Sr No | Machine Name | Make | Model  |
|-------|--------------|------|--------|
| 1     | 1221         | WMW  | SABU   |
| 2     | 1222         | WMW  | 2000MM |
| 3     | 1223         | WMW  | 2000MM |
| 4     | 1224         | WMW  | 2000   |
| 5     | 1225         | WMW  | 800    |

**CNC Gear Hobbing Machine**

| Sr No | Machine Name | Make | Model |
|-------|--------------|------|-------|
| 1     | B52          | HMT  | H250  |

## CNC Gear Shaving Machine

| Sr No | Machine Name | Make    | Model    |
|-------|--------------|---------|----------|
| 1     | B51          | SICHMAT | RASO 200 |

## Gear Hobbing Machine

| Sr No | Machine Name | Make         | Model          |
|-------|--------------|--------------|----------------|
| 1     | 1053         | PFAUTER      | PA210          |
| 2     | 10127        | CIMA         | P3             |
| 3     | 10129        | LIEBHERR     | L300           |
| 4     | 10510        | PFAUTER      | SH200(SHOBBER) |
| 5     | 10511        | PFAUTER      | SH300(SHOBBER) |
| 6     | 10512        | PFAUTER      | RA100          |
| 7     | 10513        | PFAUTER      | RA200          |
| 8     | 10514        | PFAUTER      | P253           |
| 9     | 10517        | PFAUTER      | P160           |
| 10    | 10518        | HURTH        | WF10           |
| 11    | 10519        | PFAUTER      | SH200(SHOBBER) |
| 12    | 10520        | CIMA         | P4UAR          |
| 13    | 10521        | CIMA         | P4UAR          |
| 14    | 10522        | LIEBHERR-HMT | H-250          |
| 15    | 10523        | LIEBHERR     | L300           |
| 16    | 10524        | CUGIR        | FD400          |
| 17    | 10526        | KOFFER       | 136            |
| 18    | 10527        | WMW          | ZFWZ630        |
| 19    | 10528        | WMW          | ZFWZ315        |
| 20    | 10529        | HURTH        | WF10           |
| 21    | 10530        | WMW          | ZFWZ250        |

|    |       |              |                |
|----|-------|--------------|----------------|
| 22 | 10531 | MORAT        | B9             |
| 23 | 10532 | PFAUTER      | SH200(SHOBBER) |
| 24 | 10533 | PFAUTER      | SH300(SHOBBER) |
| 25 | 10535 | WMW          | ZFWZ-800/2     |
| 26 | 10536 | LORENZ       | LF315          |
| 27 | 10537 | LORENZ       | LF315          |
| 28 | 10538 | LORENZ       | LF315          |
| 29 | 10539 | TOS          | OFA16A         |
| 30 | 1054  | PFAUTER      | SH300(SHOBBER) |
| 31 | 10540 | TOS          | OFA16A         |
| 32 | 10541 | STANKO       | 1250           |
| 33 | 10543 | STANKO       | 300            |
| 34 | 10544 | SHOBBER      | TOS400         |
| 35 | 10545 | PFAUTER      | SH200(SHOBBER) |
| 36 | 10547 | PFAUTER      | PA180          |
| 37 | 10548 | PFAUTER      | RA200          |
| 38 | 10549 | PFAUTER      | P180           |
| 39 | 1055  | PFAUTER      | SH300(SHOBBER) |
| 40 | 10550 | LIEBHERR     | L600           |
| 41 | 10551 | CUGIR        | FD400          |
| 42 | 10552 | HMT LIEBHERR | H400           |
| 43 | 10553 | CHURCHILL    | RH8            |
| 44 | 10554 | COOPER       | P630           |
| 45 | 10555 | CLEVELAND    | CLEVELAND      |
| 46 | 10558 | HMT LIEBHERR | H400           |
| 47 | 10559 | PFAUTER      | PA210CNC       |
| 48 | 1056  | PFAUTER      | SH180(SHOBBER) |
| 49 | 10563 | HURTH        | WF10           |

|    |       |               |                  |
|----|-------|---------------|------------------|
| 50 | 10564 | HURTH         | WF10             |
| 51 | 10567 | HURTH         | WF10             |
| 52 | 10569 | HURTH         | WF10             |
| 53 | 1057  | PFAUTER       | SH300(SHOBBER)   |
| 54 | 10570 | HURTH         | WF10             |
| 55 | 10571 | HURTH         | WF10             |
| 56 | 10572 | LIEBHERR      | LC152            |
| 57 | 10574 | WMW           | ZFWZ250          |
| 58 | 10575 | WMW           | ZFWZ250          |
| 59 | 10576 | WMW           | ZFWZ250          |
| 60 | 10577 | WMW           | ZFWZ250          |
| 61 | 10578 | CHURCHILL     | RH8              |
| 62 | 10579 | LEES BRANDNER | 7HD              |
| 63 | 1058  | PFAUTER       | SH300(SHOBBER)   |
| 64 | 10581 | GLEASON       | 782              |
| 65 | 1059  | PFAUTER       | SH200(SHOBBER)   |
| 66 | B01   | KASHIFUJI     | CNC              |
| 67 | B02   | KASHIFUJI     | CNC              |
| 68 | B03   | KASHIFUJI     | CNC              |
| 69 | B04   | KASHIFUJI     | CNC              |
| 70 | B05   | LIEBHERR      | L400             |
| 71 | B06   | PFAUTER       | P400             |
| 72 | B07   | PFAUTER       | P160             |
| 73 | B08   | WMW           | ZFWZ630          |
| 74 | B20   | KASHIFUJI     | HB02             |
| 75 | B23   | MITSUBISHI    | HB01             |
| 76 | B25   | COOPER        | P251             |
| 77 | B29   | Seiwa         | Horizontal (CNC) |

|    |     |              |        |
|----|-----|--------------|--------|
| 78 | B33 | PFAUTER      | PE150  |
| 79 | B34 | PFAUTER      | PE150  |
| 80 | B35 | LIEBHERR     | L630   |
| 81 | B43 | HURTH        | WF300  |
| 82 | B46 | HMT LIEBHERR | H400   |
| 83 | B50 | CNC          | KB 300 |

**Gear Shaping Machine**

| Sr No | Machine Name | Make      | Model      |
|-------|--------------|-----------|------------|
| 1     | 10115        | LIEBHERR  | WS1        |
| 2     | 1011         | LIEBHERR  | WS1        |
| 3     | 10110        | DRUMMONEL | MAXICUT150 |
| 4     | 10111        | LIEBHERR  | WS1        |
| 5     | 10113        | LORENZ    | LU300      |
| 6     | 10114        | TOS       | OHA12A     |
| 7     | 10116        | LIEBHERR  | WS1        |
| 8     | 10117        | TOS       | OHO50      |
| 9     | 10118        | LIEBHERR  | WS1        |
| 10    | 10119        | LIEBHERR  | WS1        |
| 11    | 1012         | LIEBHERR  | WS1        |
| 12    | 10120        | LIEBHERR  | WS1        |
| 13    | 10121        | FELLOWS   | 800        |
| 14    | 1013         | LIEBHERR  | WS1        |
| 15    | 1014         | LIEBHERR  | WS1        |
| 16    | 1015         | LORENZ    | LS200      |
| 17    | 1016         | LORENZ    | LS200      |
| 18    | 1018         | LORENZ    | LS-150     |

|    |      |          |        |
|----|------|----------|--------|
| 19 | 1019 | STANKO   | STANKO |
| 20 | B27  | LIEBHERR | WS1    |
| 21 | B30  | LORENZ   | SN4    |
| 22 | B31  | LORENZ   | SN4    |

**Gear Shaving Machine**

| Sr No | Machine Name | Make              | Model       |
|-------|--------------|-------------------|-------------|
| 1     | 1021         | RED RING          | GCU10       |
| 2     | 10211        | RED RING          | GCU         |
| 3     | 10212        | RED RING          | GCU         |
| 4     | 10213        | RED RING          | GCU10       |
| 5     | 10214        | RED RING          | REDRING     |
| 6     | 10215        | SICHMAT           | NRSU460     |
| 7     | 1022         | RED RING          | GCU10       |
| 8     | 1024         | SICHMAT           | SICHMATSP32 |
| 9     | 1025         | CHURCHILL REDRING | GCV8        |
| 10    | 1026         | RED RING          | 620         |
| 11    | 1027         | STANKO            | RUSSIAN     |
| 12    | 1028         | HURTH             | ZST7        |
| 13    | B 18         | KANZAKI           | SV9         |
| 14    | B09          | STANKO            | 400         |
| 15    | B10          | STANKO            | 400         |
| 16    | B11          | STANKO            | 400         |
| 17    | B12          | CHURCHILL         | 320         |
| 18    | B13          | KANZAKI           | 400         |
| 19    | B14          | KANZAKI           | 400         |
| 20    | B15          | KANZAKI           | 400         |

|    |     |                 |          |
|----|-----|-----------------|----------|
| 21 | B16 | mitsubishi      | FA30     |
| 22 | B17 | HURTH           | ZS350    |
| 23 | B19 | KANZAKI         | SV10     |
| 24 | B21 | KANZAKI         | SV08     |
| 25 | B26 | KANZAKI         | 400      |
| 26 | B32 | Pfauter-Kanzaki | 400P CNC |
| 27 | B36 | Kanzaki (CNC)   | GSK400   |
| 28 | B37 | Kanzaki(NC)     | 400      |
| 29 | B39 | HURTH           | ZS240    |
| 30 | B41 | SICHMAT         | RASO 220 |
| 31 | B42 | HURTH           | ZSA320   |
| 32 | B44 | KANZAKI         | 400      |
| 33 | B48 | STANKO          | 400      |
| 34 | B49 | STANKO          | 400      |
| 35 | B54 | HURTH           | ZSA220   |
| 36 | B55 | HURTH           | ZS350    |

**Gear Testing Machine**

| Sr No | Machine Name | Make      | Model  |
|-------|--------------|-----------|--------|
| 1     | 10610        | KLINGBERG | PWF300 |
| 2     | 10611        | KLINGBERG | 1200   |
| 3     | 10612        | MAAG      | PH100  |
| 4     | 1062         | MAAG      | PH60   |
| 5     | 1063         | MAAG      | PH60   |
| 6     | 1064         | MAHAR     | 891S   |
| 7     | 1065         | MAHAR     | 891S   |
| 8     | 1066         | KLINGBERG | PFS600 |



|    |      |              |           |
|----|------|--------------|-----------|
| 9  | 1067 | KLINGBERG    | PFS600    |
| 10 | 1068 | KLINGBERG    | PNC40CNC  |
| 11 | 1069 | HOFLER       | EFRS401MZ |
| 12 | B38  | Klingelnberg | 1250      |

**Hob Sharpening Machine**

| Sr No | Machine Name | Make      | Model   |
|-------|--------------|-----------|---------|
| 1     | 10811        | KAPP      | ASA305  |
| 2     | 1081         | KLINGBERG | AGW-232 |
| 3     | 10810        | KLINGBERG | GW30    |
| 4     | 1082         | STANKO    | 250     |
| 5     | 1083         | HURTH     | SRS400  |
| 6     | 1084         | HURTH     | SRS400  |
| 7     | 1085         | KAPP      | AS203   |
| 8     | 1086         | KAPP      | ASA305  |
| 9     | 1087         | KAPP      | ASA305  |
| 10    | 1088         | WMW       | SWFW250 |
| 11    | 1089         | KLINGBERG | ASW230  |
| 12    | B45          | KAPP      | KS204   |

**Spline Cutting Machine**

| Sr No | Machine Name | Make  | Model |
|-------|--------------|-------|-------|
| 1     | 1101         | HURTH | KF32  |
| 2     | 1102         | HURTH | KF32  |
| 3     | 1103         | HURTH | KF32  |

**Spline Rolling Machine**

| Sr No | Machine Name | Make | Model |
|-------|--------------|------|-------|
| 1     | 1071         | GROB | ZRM9  |

**Tooth Rounding and Champering Machine**

| Sr No | Machine Name | Make         | Model        |
|-------|--------------|--------------|--------------|
| 1     | 1097         | SAIMPUTENSLI | SAIMPUTENSLI |
| 2     | 1097         | SAIMPUTENSLI | SM2TA        |
| 3     | 1091         | HURTH        | ZK5          |
| 4     | 1092         | HURTH        | ZK5          |
| 5     | 1093         | PRAWEMA      | ZEA          |
| 6     | 1094         | SCHIESS      | ERNFO1       |
| 7     | 1095         | HURTH        | ZK5          |
| 8     | 1098         | HEY          | HEY-10       |

**Grinding Machine**

**Centreless Grinding Machine**

| Sr No | Machine Name | Make           | Model                        |
|-------|--------------|----------------|------------------------------|
| 1     | 1141         | HERMING HAUSEN | HERMINGHAUSENSR40HT4C        |
| 2     | 1142         | CINCINNATI     | CINCINNATIMILACRONMODEL220-8 |

**Cylindrical Grinder**

| Sr No | Machine Name | Make    | Model   |
|-------|--------------|---------|---------|
| 1     | 1191         | CC      | 250*700 |
| 2     | 11910        | VERNIER | VERNIER |
| 3     | 11911        | WMW     | WMW     |

|    |       |        |         |
|----|-------|--------|---------|
| 4  | 11913 | STANKO | STANKO  |
| 5  | 1192  | ZOKKA  | ZOKKA   |
| 6  | 1193  | AVION  | AVION   |
| 7  | 1194  | SCHAUT | CNC     |
| 8  | 1195  | TOS    | ANGULAR |
| 9  | 1196  | LANDIS | ANGULAR |
| 10 | 1197  | STANKO | STANKO  |
| 11 | 1198  | MORARA | MORARA  |

**Gear Grinding Machine**

| Sr No | Machine Name | Make        | Model       |
|-------|--------------|-------------|-------------|
| 1     | 10411        | MAAG ZURICH | HSS-10      |
| 2     | 10412        | STANKO      | 350         |
| 3     | 10414        | REISHAUER   | AZO         |
| 4     | 10415        | WMW NILES   | ZSTZ08EGCNC |
| 5     | 1043         | REISHAUER   | OZA         |
| 6     | 1044         | REISHAUER   | ZB          |
| 7     | 1046         | STANKO      | 450         |
| 8     | 1047         | STANKO      | 450         |
| 9     | 1049         | REISHAUER   | RZP         |
| 10    | B22          | Lorenz      | SP02        |
| 11    | B28          | REISHAUER   | NZA(CNC)    |
| 12    | B53          | REISHAUER   | AZA         |

**Internal Grinding Machine**

| Sr No | Machine Name | Make     | Model  |
|-------|--------------|----------|--|
| 1     | 1171         | OVERBECK | OVERBECK 400 IR 150 SPH X 160 MM<br>SCHLEIFTIEFE |

|   |      |           |                          |
|---|------|-----------|--------------------------|
| 2 | 1172 | CINNATI   | CINNATIMILACRONHEALD273A |
| 3 | 1173 | VOUMARD   | 5ALP                     |
| 4 | 1174 | REINECKER | ISA-110                  |
| 5 | 1175 | NOVA      | NOVARESE10/150           |
| 6 | 1176 | NOVA      | NOVARESE10/150           |
| 7 | 1177 | NOVA      | 10/150                   |
| 8 | 1178 | JUNG      | LP4Z                     |
| 9 | 1179 | VOUMARD   | 6A                       |

**Spline Grinding Machine**

| Sr No | Machine Name | Make | Model |
|-------|--------------|------|-------|
| 1     | 1151         | KAAP | KAAP  |

**Surface Grinding Machine**

| Sr No | Machine Name | Make            | Model           |
|-------|--------------|-----------------|-----------------|
| 1     | 1181         | BLOHM           | HFS 6           |
| 2     | 1182         | STANKO          | 3G71            |
| 3     | 1183         | STANKO          | 3G71M           |
| 4     | 1184         | STANKO          | 200-800         |
| 5     | 1186         | BROWNE & SHARPE | BROWNE&SHARPE#2 |
| 6     | 1188         | ALPHA           | ALPHA500X1500   |
| 7     | 1189         | ABWOOD          | ABWOOD          |

**Thread Grinding Machine**

| Sr No | Machine Name | Make      | Model |
|-------|--------------|-----------|-------|
| 1     | 1131         | REISHAUER | NRK   |
| 2     | 1132         | LINDNER   | 2000  |

|   |      |           |          |
|---|------|-----------|----------|
| 3 | 1134 | KLINGBERG | HSS350K  |
| 4 | 1135 | WMW       | GSUPC320 |
| 5 | B40  | STANKO    | 5822M    |

**CNC**

**CNC Horizontal Machining Centre (HMC)**

| Sr No | Machine Name | Make    | Model |
|-------|--------------|---------|-------|
| 1     | 1111         | DECKEL  | DC30  |
| 2     | 1112         | CELLCON | 500   |
| 3     | 1113         | STEINAL | BZ-26 |

**CNC Lathe**

| Sr No | Machine Name | Make      | Model        |
|-------|--------------|-----------|--------------|
| 1     | 1231         | IKEGAI    | TCR15        |
| 2     | 12310        | HARDINGE  | CONQUESTT-42 |
| 3     | 12311        | MAZAK     | QUICKSLANT20 |
| 4     | 12312        | SMT       | SMT          |
| 5     | 12313        | SMT       | SMT          |
| 6     | 12314        | EMCO      | CONQUESTT-51 |
| 7     | 12315        | BENZINGER | TNL          |
| 8     | 12316        | BIGELA    | BIGELA       |
| 9     | 12317        | WASINO    | LG-7         |
| 10    | 12318        | MOREISIKI | ZL15S        |
| 11    | 12319        | MOREISIKI | ZL15M        |
| 12    | 1232         | IKEGAI    | AX25N        |
| 13    | 12320        | MOREISIKI | ZL15S        |
| 14    | 1233         | WASINO    | LG-7         |

|    |      |          |                 |
|----|------|----------|-----------------|
| 15 | 1234 | HARDINGE | SUPERSLANT3AXIS |
| 16 | 1235 | HARDINGE | SUPERSLANT3AXIS |
| 17 | 1236 | HARDINGE | HARDINGE        |
| 18 | 1237 | HARDINGE | CONQUESTT-42    |
| 19 | 1238 | HARDINGE | HARDINGE        |
| 20 | 1239 | HARDINGE | CONQUESTT-42    |

### CNC Vertical Machining Centre (VMC)

| Sr No | Machine Name | Make         | Model        |
|-------|--------------|--------------|--------------|
| 1     | 1241         | CHIRON       | FZ12L        |
| 2     | 12410        | STAMA        | 5AXIS        |
| 3     | 1242         | CHIRON       | FZ22L        |
| 4     | 1243         | OKK          | MCV-300      |
| 5     | 1244         | BEVER        | 500*1000     |
| 6     | 1245         | VICTOR       | VCENTER4S    |
| 7     | 1246         | BRIGPORT     | INTERACT412X |
| 8     | 1247         | LEADWELL     | MCVOP        |
| 9     | 1248         | LEADWELL     | MCVOP        |
| 10    | 1249         | HITACHISEIKI | VA40         |

### Drill Tap Centre

| Sr No | Machine Name | Make    | Model        |
|-------|--------------|---------|--------------|
| 1     | 1114         | FANUC   | FANUC        |
| 2     | 1251         | SUGINO  | SELFCENTERV6 |
| 3     | 1252         | BROTHER | TC255        |
| 4     | 1254         | OKUMA   | DCN4         |
| 5     | 1255         | OKUMA   | DCN4         |

**Various Machines**

**BROACHING MACHINES**

| Sr No | Machine Name | Make       | Model |
|-------|--------------|------------|-------|
| 1     | 1451         | WEATHERLEY | 15Ton |

**Horizontal Boring Machine**

| Sr No | Machine Name | Make  | Model |
|-------|--------------|-------|-------|
| 1     | 1281         | UNION | 130/5 |

**Jig Boring Machine**

| Sr No | Machine Name | Make   | Model             |
|-------|--------------|--------|-------------------|
| 1     | 1261         | WMW    | BKOE630X1000/1PA2 |
| 2     | 12610        | HAUSER | JIGGRINDER3SM     |
| 3     | 12611        | HAUSER | 3SMO              |
| 4     | 12612        | PERRIN | 400*600           |
| 5     | 1262         | WMW    | 630*1000          |
| 6     | 1264         | WMW    | 630*1400          |
| 7     | 1265         | SIP    | 6A                |
| 8     | 1266         | SIP    | 5                 |
| 9     | 1267         | SIP    | 6A                |
| 10    | 1268         | SIP    | 7ACN              |
| 11    | 1269         | HAUSER | JIGGRINDER        |

**Milling Machine**

| Sr No | Machine Name | Make  | Model  |
|-------|--------------|-------|--------|
| 1     | 1201         | ABENE | VHF320 |

|    |      |                 |               |
|----|------|-----------------|---------------|
| 2  | 1202 | DECKEL          | KF1           |
| 3  | 1203 | GAMBIN          | 3M            |
| 4  | 1205 | ARNO            | NO4           |
| 5  | 1206 | FAGIMA          | MMO130        |
| 6  | 1207 | WMW             | FSS315        |
| 7  | 1210 | BROWN AND SHARP | S/N:506-20-32 |
| 8  | 1211 | STARRAG         | STARRAG       |
| 9  | 1214 | ITALIAN         | ITALIAN       |
| 10 | 1215 | ARNO            | 30            |

**Presses**

| Sr No | Machine Name | Make   | Model  |
|-------|--------------|--------|--------|
| 1     | 1341         | WMW    | PASU40 |
| 2     | 1342         | WMW    | PASU40 |
| 3     | 1343         | SCHMID | T200   |

**Radial Drilling Machine**

| Sr No | Machine Name | Make   | Model |
|-------|--------------|--------|-------|
| 1     | 1122         | STANKO | 80MM  |

**Relieving Lathe Machine**

| Sr No | Machine Name | Make | Model     |
|-------|--------------|------|-----------|
| 1     | 1271         | WMW  | NO3       |
| 2     | 1272         | WMW  | DH250X630 |
| 3     | 1273         | WMW  | DH250/3   |



**Thread Rolling Machine**

| <b>Sr No</b> | <b>Machine Name</b> | <b>Make</b> | <b>Model</b> |
|--------------|---------------------|-------------|--------------|
| 1            | 1321                | WMW         | UPW125       |
| <b>Other</b> |                     |             |              |